
DMG MORI NLX 2500 SY

Lathe · CNC lathe



Article number	**89-001898**
Condition	**Used machine**
Year of manuf.	**2017**
Control	**Sonstige MAPPS 730 UM - CELOS**
Turning diam.	**271 mm**
Turning length	**705 mm**

Mainspindle:

Technology	Motorspindle
Speed	4.000 rpm
Power (max.)	18,5 kW
Bar capacity	80 mm
Workpiececlamping	3-Jaw chuck, Kitagawa BB 210

Subspindle:

Technology	Motorspindle
Speed	6.000 rpm
Power (max.)	11 kW
Workpiececlamping	3-Jaw chuck, Kitagawa B 206
Movement in B	734 mm
Rapid travers in B	30 m/min

Toolcarrier (X/Y/Z):

Technology	Turret with 12 stations
Taper	BMT65
Tooldive	10.000 rpm, 5,5 kW, 40,5 Nm
Movement in X/Y/Z	260/100/795 mm
Rapid travers in X/Y/Z	30/10/30 m/min

Tel. +49 (0) 8142 / 44 87 - 100
Fax +49 (0) 8142 / 44 87 - 155
info@gs-wzm.de
www.gs-werkzeugmaschinen.de

Gläsener + Schmidt GmbH
Gewerbering 6
82140 Olching
Deutschland

Subject to prior sale and technical errors.

Equipment/Accessory:

Chipmanagement	Chip conveyor
Coolingmanagement	Internal coolant pump with Filter and Highpressure
Toolmeasurement	Manual Measuringarm, Marposs TT30
Rawmaterialfeed	Interface Barloader prepared (Circuit board)
Finsihedpartremoval	Part catcher with collecting box
Automation	Robotinterface (Robo2Go)
Oilmistseparation	Interface mechanical prepared
Further Equipment	Trafo
Further Accessory	Misc. used static and driven Toolholder


Tel. +49 (0) 8142 / 44 87 - 100
Fax +49 (0) 8142 / 44 87 - 155
info@gs-wzm.de
www.gs-werkzeugmaschinen.de


Gläsener + Schmidt GmbH
Gewerbering 6
82140 Olching
Deutschland

Subject to prior sale and technical errors.


Product images














Tel. +49 (0) 8142 / 44 87 - 100
Fax +49 (0) 8142 / 44 87 - 155
info@gs-wzm.de
www.gs-werkzeugmaschinen.de

Gläsener + Schmidt GmbH
Gewerbering 6
82140 Olching
Deutschland

Subject to prior sale and
technical errors.













Tel. +49 (0) 8142 / 44 87 - 100
Fax +49 (0) 8142 / 44 87 - 155
info@gs-wzm.de
www.gs-werkzeugmaschinen.de

Gläsener + Schmidt GmbH
Gewerbering 6
82140 Olching
Deutschland

Subject to prior sale and technical errors.